

Technical Bulletin



NP01	TB0006-2016	Élan Motorsports Technologies	
From:	Robert Lindsey – Project Engineer, NP01		
Subject:	Upright Improvement	Date:	15 Feb 2016

Attention all Élan NP01 customers up to chassis # 15:

Some customers have experienced fracturing of the splitter at its joint to the “Splitter Base”. To prevent this we have added reinforcement to all parts after chassis #15.

If your splitter lacks the update you will receive a reinforcement strip to be glued into the splitter as shown below.

