

# Technical Bulletin



<b>NP01</b>	<b>TB0011-2016</b>	<b>Élan Motorsports Technologies</b>	
<b>From:</b>	<b>Robert Lindsey – Project Engineer, NP01</b>		
<b>Subject:</b>	<b>Main Fuse Replacement</b>	<b>Date:</b>	<b>8 March 2016</b>

---

Attention all Élan NP01 customers:

Some customers have reported failure of the 15 amp “Main” fuse. Please note that this fuse may be increased to 20 amps without risk. Please contact Elan if this increase still results in a blown fuse.