

Technical Bulletin



NP01	TB0002-2015	Élan Technologies	
From:	Robert Lindsey – Project Engineer		
Subject:	CV Boot Solution	Date:	17 December 2015

Attention all Élan NP01 customers:

It has been noted that the factory outboard CV boot shows inconsistent durability in this application. Elan is supplying an improved part for installation by the customer.

- Elan Part # PY-0623 – CV BOOT, OUTER

In addition, Elan recommends SWEPCO 101 grease for use in the outboard CV joint.